




Technology Update

Richard Petrie | CTO



Agenda











Operations Update



Operations

Measuring Success

Deskpro, direct member feedback

Member survey

LINX Community








Self-Service






Deskpro Member Feedback





Member Satisfaction Survey















LINX Community

Portal

Home

- O) Members
- Acceptable Use Policy
- General
- Mailing Lists
- News and Events
- Resources
- Report a Bug

© Copyright 2024

Welcome to LINX Community

Q Search for anything...

Join the Community

LINX Community is your hub to connect with members around the globe. Join spaces and mailing lists to make sure you're up to date with the latest discussions and LINX news.

You will be notified via email for updates in any channels you have joined, or direct messages you receive. To manage your notification preferences, simply visit the notification area within your account preferences.

Please familiarise yourself with our Acceptable Use Policy before starting to use LINX Community.

Please be aware that some pages are public, and this will be clearly marked within the channel introduction.

Join a Space

Acceptable Use Policy







LAN	Incidents
Systems	1
LON1	3 (1 Problem)
LON2	0
LINX Manchester	0
LINX Wales	0
LINX Scotland	0
LINX NoVA	0
JEDIX	1 (Management)
ManxIX	0
Nairobi	1 (At Risk)





Shared on LINX Community

LINX LON1, Digital Realty site (LON1), Line card issue and replacement on Juniper core3.in2, also impacting the Route Server rs1. [10th April] and [13th April] LINX LON1, Digital Realty site (LON1), FPC errors on Juniper mx10k device, core3.in2, line card issues [29th March]

LINX System, Network Automation offline. [20th March]



LINX LON1, Digital Realty site (LON1), FPC errors on Juniper MX10K 29/03 ASIC errors observed on FPC3 PIC0 Reoccurrence on 10/04

Faulty FPC replaced on 13/04

Resulting in PIC auto disabling

JTAC advise to

JTAC advise to reboot FPC to restore, and to monitor

JTAC advise to replace FPC, and to monitor.

As PIC0 of FPC3 had rs1.lon1 corrected, sessions to the RS were impacted



LON1 Project Update



LON1 Update

What are we planning to do now

April

Complete THN migrations

Begin deployment of SR-2se's (enables 400G at these sites)

- RBS migration
- TCM migration
- TCA migration

May

- Installation and commissioning of new SR2s at:
 - TCM, THE & TH2

June

- Member moves to Nokia SR-2SE's
 - TCM migration(following LINX meeting)
 - THE migration
 - THN2 migration



LON1 Update

What are we planning to do now

July & August

- EQ4 migration some moves within existing racks required for this
- TCA migration but complications on space rack depth resulting in needing to migrate to new racks before migrating.
- Snagging and documentation clean up, ISO readiness



Other Projects

♦ NoVA

Migration to Nokia 7220 IXRs completed

New members connected

Traffic > 100GE

♦ ISO27001:2022

- Readiness stage
- Core ISMS audit in August
- DC audits in September
- Update in November

Riyadh

- Install done
- Network built and waiting on stable redundant power setup from Centre3
- Members ready to connect





Route Serves



Route Serves

OpenBGPd route-servers

- Positive news on wider adoption of OpenBGPd, including IXP Manager support
- Progress from Mo on lab testing, testing for 1000+ Peers before we go for LON1 deployment (v8.4)

BIRD2 upgrades

- All sites upgraded and moved to done
- All Route Collector to be moved to BIRD2 in Q2





Route Serves

AliceLG

- Version 6.0 has a resource issue
- Testing 6.1.0
 - This is looking promising
 - We have now deployed as of the 3rd May 2024 on route collectors



Mail List Manager



Moving the @lists.linx.net email communication to Mailman, the GNU Mailing List Manager.



youtube.com/user/LINXnetwork